

Continue

1/2

Phoenix Award Bios V6.00pg Windows 10 Graphics Driver

It is possible that your BIOS / Motherboard driver is not compatible with the newer version of Windows.. If you want help, you must identify your motherboard You can help whit a diagnostics and information system software like EVEREST Home Edition (it is a free).. What you need is the maker and model of motherboard that you have This will be written on the board itself (usually around the center), so if you open the case you can read it.. My mobo is MSi K8N NEO4 Platinum [MS-7125] 1 0 I downloaded update for BIOS, and i got 4 files: 7125 - Text document that says what is that update doing.. It says: This BIOS fixes the following problem of the previous version: - Improve compatibility problem with nVidia graphic card - Improve stability problem when doing overclock behavior.

Posted on Oct 18, 2009 'AwardBIOS v6 00PG' is not enough information to find a BIOS upgrade.. This program provide you that will id mosthardware onboard a MB You can download here: Run the program and then: Click on Computer Click on Summary Right hand window (hardware) if the text is BLUE this is a link to the web site for that particular hardware.. After you upgrade your computer to Windows 10, if your Award BIOS / Motherboard Drivers are not working, you can fix the problem by updating the drivers.. If you have additional questions or need further help, please post a SUMMARY report from Everest.. Product Information BIOS Upgrades Posted on Mar 04, 2010 • 84 Answers SOURCE: Phoenix is a BIOS manifacteur, not a motherboard.

e10c415e6f